



**POWERWIND**

*Your power in wind*



POWERWIND is leading **wind turbine installation contractor** offering heavy cranaage and mechanical / electrical installation services to worldwide known wind turbine suppliers in the market including, Enercon, Nordex, Siemens, Vestas, GE and Goldwind.

Our highly skilled technicians and engineers have vast experience working for all the major wind turbine manufacturers.

As POWERWIND, our goal is to provide quality services that exceed the expectations of our esteemed customers by investing all their gains in assets and development of the company, and to establish a good reputation in the industry by establishing long-term good relations with our customers based on respect, honesty and good business ethics.





# OUR CERTIFICATES

**CERTIFICATE OF REGISTRATION**

  
SYNDICATE OF INTERNATIONAL SYSTEM

This Certificate has been awarded to

**POWERWIND RÜZGAR TÜRBİNLERİ  
SERVİS SANAYİ TİCARET LİMİTED ŞİRKETİ**  
MANSUROĞLU MAH. ANKARA CAD. NO:81/17 BAYRAKLI / İZMİR / TÜRKİYE

In recognition of the organization's Managements System which complies with

**ISO 9001:2015**

The scope of activities covered by this certificate is defined below

WIND TURBINE INSTALLATION, SERVICE, MAIN COMPONENT EXCHANGE  
RÜZGAR TÜRBİNLERİ KURULUM, SERVİS, PARÇA DEĞİŞİMİ

Certificate Number: SISTURO0620191971  
Date of Issue of Original Certificate: 12.06.2019  
Date of Issue of Latest Certificate: 12.06.2019  
Expiry Date: 11.06.2020

  
*Managing Director*

Note: This certificate is valid only if produced with the continuation letter after the surveillance is carried out successfully.

The Organization's documentation and Implementation has been reviewed and found to comply with the relevant standard rules. This certificate of Registration is based on the evaluation of the mentioned scope given above. Organization is responsible for maintaining the responsibilities of the relevant standard rules. Any significant changes in the scope of the certification or standard referred above render this certificate invalid. This is an accredited certificate issued by SIS Certifications Pvt. Ltd. sanctioned for issue by International Accreditation Services, 3060 Saturn Street Suite 100 Brea, California 92821-1732, USA.

Email us : support@siscertifications.com, info@siscertifications.co.in, Call: +90-9054721048  
Web : <http://www.siscertifications.co.in>, [www.siscertifications.com](http://www.siscertifications.com)  
The status of this certificate can be verified on "<http://www.siscertifications.co.in>".

Issue No. : 01


**CERTIFICATE OF REGISTRATION**

  
SYNDICATE OF INTERNATIONAL SYSTEM

This Certificate has been awarded to

**POWERWIND RÜZGAR TÜRBİNLERİ  
SERVİS SANAYİ TİCARET LİMİTED ŞİRKETİ**  
MANSUROĞLU MAH. ANKARA CAD. NO:81/17 BAYRAKLI / İZMİR / TÜRKİYE

In recognition of the organization's Managements System which complies with

**ISO 14001:2015**

The scope of activities covered by this certificate is defined below

WIND TURBINE INSTALLATION, SERVICE, MAIN COMPONENT EXCHANGE  
RÜZGAR TÜRBİNLERİ KURULUM, SERVİS, PARÇA DEĞİŞİMİ

Certificate Number: SISTURO062019468  
Date of Issue of Original Certificate: 12.06.2019  
Date of Issue of Latest Certificate: 12.06.2019  
Expiry Date: 11.06.2020

  
*Managing Director*

Note: This certificate is valid only if produced with the continuation letter after the surveillance is carried out successfully.

The Organization's documentation and Implementation has been reviewed and found to comply with the relevant standard rules. This certificate of Registration is based on the evaluation of the mentioned scope given above. Organization is responsible for maintaining the responsibilities of the relevant standard rules. Any significant changes in the scope of the certification or standard referred above render this certificate invalid. This is an accredited certificate issued by SIS Certifications Pvt. Ltd. sanctioned for issue by International Accreditation Services, 3060 Saturn Street Suite 100 Brea, California 92821-1732, USA.

Email us : support@siscertifications.com, info@siscertifications.co.in, Call: +90-9054721048  
Web : <http://www.siscertifications.co.in>, [www.siscertifications.com](http://www.siscertifications.com)  
The status of this certificate can be verified on "<http://www.siscertifications.co.in>".

Issue No. : 01


**CERTIFICATE OF REGISTRATION**

  
SYNDICATE OF INTERNATIONAL SYSTEM

This Certificate has been awarded to

**POWERWIND RÜZGAR TÜRBİNLERİ  
SERVİS SANAYİ TİCARET LİMİTED ŞİRKETİ**  
MANSUROĞLU MAH. ANKARA CAD. NO:81/17 BAYRAKLI / İZMİR / TÜRKİYE

In recognition of the organization's Managements System which complies with

**ISO 45001:2018**

The scope of activities covered by this certificate is defined below

WIND TURBINE INSTALLATION, SERVICE, MAIN COMPONENT EXCHANGE  
RÜZGAR TÜRBİNLERİ KURULUM, SERVİS, PARÇA DEĞİŞİMİ

Certificate Number: SISTURO062019156  
Date of Issue of Original Certificate: 19.06.2019  
Date of Issue of Latest Certificate: 19.06.2019  
Expiry Date: 18.06.2020

  
*Managing Director*

Note: This certificate is valid only if produced with the continuation letter after the surveillance is carried out successfully.

The Organization's documentation and Implementation has been reviewed and found to comply with the relevant standard rules. This certificate of Registration is based on the evaluation of the mentioned scope given above. Organization is responsible for maintaining the responsibilities of the relevant standard rules. Any significant changes in the scope of the certification or standard referred above render this certificate invalid. This is an accredited certificate issued by SIS Certifications Pvt. Ltd. sanctioned for issue by International Accreditation Services, 3060 Saturn Street Suite 100 Brea, California 92821-1732, USA.

Email us : support@siscertifications.com, info@siscertifications.co.in, Call: +90-9054721048  
Web : <http://www.siscertifications.co.in>, [www.siscertifications.com](http://www.siscertifications.com)  
The status of this certificate can be verified on "<http://www.siscertifications.co.in>".

Issue No. : 01









**INSTALLATION**



**COMPONENT EXCHANGE**



**SERVICE**



**RETROFITS**

**PowerwindRüzgar Türbinleri Servis San. Tic. Ltd. Şti.**

Mansuroğlu Mah. Ankara Cad. No:81 Bayraklı TowerKat:4 No:17 Bayraklı /İzmir/ Türkiye Tel: +90 232 502 14 14 Fax: +90 232 502 1425

[www.powerwindservice.com/](http://www.powerwindservice.com/) / [info@powerwindservice.com](mailto:info@powerwindservice.com)



# INSTALLATION PROJECTS



#### NORDEX INSTALLATION PROJECTS

PROJECT NAME	LOCATION	WTG TYP / QUANTITY
Karadağ	Çeşme / Izmir	N117 / 6 Units
Susurluk	Susurluk / Balıkesir	N117 / 2 Units (demontage and montage)
Susurluk	Susurluk / Balıkesir	N117 / 1 Unit
Kurtini	Kurtini / Mersin	N117 / 6 Units
Dilek	Dilek / Kahraman Maraş	N117 / 5 Units
Akbük	Akbük / Aydın	N117 / 6 Units
Çanta	Silivri / İstanbul	N117 / 2 Units
Silivri	Silivri / İstanbul	N117 / 1 Unit
AyvaRES	Ayvalık / Balıkesir	N117 / 3 Units
MarmaraRES	Bandırma/Balıkesir	N133 / 1 Unit
Özbek	Özbek / Hatay	N133 / 5 Units





#### INSTALLATION PROJECTS

PROJECT NAME	LOCATION	WTG TYP / QUANTITY
Bol RES	Lapseki / Çanakkale	E-53 / 1 Unit
Tepe RES	Lapseki / Çanakkale	E-53 / 1 Unit
Teta RES	Çanakkale	E-48 / 1 Unit
BHT RES	Çanakkale	E-53 / 1 Unit
Deniz RES	Çanakkale	E-53 / 1 Unit
Oytaş RES	Çanakkale	E-53 / 1 Unit
Ipek RES	Çanakkale	E-53 / 1 Unit
Kocatepe	Sandıklı / Afyon	E126 / 15 Units
Gülpınar	Gülpınar / Çanakkale	E138 / 10 Units
Soma	Soma / Manisa	E126 / 6 Units
Örlemiş	Örlemiş / İzmir	E126 / 7 Units

**INSTALLATION PROJECTS**

PROJECT NAME	LOCATION	WTG TYP / QUANTITY
Havza	Havza/Samsun	E126 / 2 Units
Karlıtepe	Karlıtepe / Hatay	E138 / 10 Units
Çaminbaşı	Çaminbaşı / Konya	E138 / 10 Units
Göktepe	Göktepe / Yalova	E138 / 1 Unit
Andoz	Andoz / Adana	E138 / 1 Unit
Gökzirve	Gökzirve / Muğla	E126 / 2 Units
Orhanlı	Orhanlı / Hatay	E126 / 3 Units
Gökzirve2	Gökzirve / Muğla	E138 / 5 Unit
Karamürsel	Karamürsel / Kocaeli	E138 / 1 Unit
Aydos	Çatalca / İstanbul	E138 / 3 Unit
Göktepe2	Göktepe / Yalova	E138 / 10 Unit
Andoz2	Andoz / Adana	E138 / 4 Unit





#### INSTALLATION PROJECTS

PROJECT NAME	LOCATION	WTG TYP / QUANTITY
Bandırma RES	Bandırma / Balıkesir	Goldwind 136/4200 / 2 Units





### GE INSTALLATION PROJECTS (Preassembly & Offloading)

PROJECT NAME	LOCATION	WTG TYP / QUANTITY
Bozüyük	Bozüyük / Bilecik	Cypress 3x / 5
Devrek	Devrek / Zonguldak	Cypress 3x / 39
Saros	Saros / Gelibolu	Cypress 3x / 27
Şapdağı	Şapdağı / Balıkesir	Cypress 3x / 5
Şile	Şile / İstanbul	Cypress 3x / 12
Güney	İnkaya / Bursa	Cypress 3x / 6
Gelibolu	Gelibolu / Çanakkale	Cypress 3x / 9







# COMPONENT EXCHANGE



## COMPONENT EXCHANGE

PROJECT NAME	LOCATION	WTG TYP / QUANTITY
Karadağ	Çeşme / Izmir	N117 / 1 x Set / Blade Replacements
ABK	Çeşme / Izmir	N117 / 6 x Set / Blade Replacements
Tayf Enerji	Ödemiş / Izmir	N117 / 5 X Set / Blade Replacements
Bilgin Enerji	Soma / Manisa	N117 / 2 X Main Bearing Replacements







#### COMPONENT EXCHANGE

PROJECT NAME	LOCATION	WTG TYP / QUANTITY
Gülpınar RES	Gülpınar / Çanakkale	E138 / 2xSet / Blade Replacement



# Vestas®

## COMPONENT EXCHANGE

PROJECT NAME	LOCATION	WTG TYP / QUANTITY
Kemalpaşa RES	Kemalpaşa / İzmir	V90 / 3xSet / Blade Replacement







**SERVICE**



## SERVICE

WIND FARM	LOCATION	SCOPE
Seferhisar	Soma, Bergama	10 X WTG Units / Mechanical Maintenance / Punch Closure Works
Edincik	Bergama	19 X WTG Units / Mechanical Maintenance / Punch Closure Works
Amasya	Susurluk	16 X WTG Units / Mechanical Maintenance / Punch Closure Works
Tokat	Karaburun / Izmir	12 X WTG / Mechanical Maintenance / Punch Closure Works
Sarpıncık	Bandırma	8 X WTG / Mechanical Maintenance / Punch Closure Works







# **SPECIAL WORKS**



## SPECIAL WORKS

WIND FARM	LOCATION	SCOPE
Seferhisar	Seferhisar / Izmir	4 X Helicoil implementation
Edincik	Bergama	Removing the broken stud bolts and Repairing treading holes via magnetic drill
Amasya	Amasya	Removing the broken stud bolts and Repairing treading holes via magnetic drill
Tokat	Tokat	Removing the broken stud bolts and Repairing treading holes via magnetic drill
Sarpıncık	Karaburun / Izmir	Removing the broken stud bolts and Repairing treading holes via magnetic drill







# MANPOWER OUTSOURCING



## MANPOWER OUTSOURCING

PROJECT NAME	MANPOWER NO	FUNCTION
Sarpıncık	1	Site HSE Manager
Edincik	1	Site HSE Manager
Bilgin Enerji	2	Mechanic and Electrical Supervisor
Dost Enerji	2	Mechanic and Electrical Supervisor
Tokat	1	Site HSE Manager
Amasya	1	Site HSE Manager
Bergama	1	Site HSE Manager







### MANPOWER OUTSOURCING

PROJECT NAME	MANPOWER NO	FUNCTION
Biga	1	Site HSE Manager
Dinar	1	Site HSE Manager
Akhisar	1	Site HSE Manager
Bergama	1	Site HSE Manager
Tire	1	Site HSE Manager
Barbaros / Tekirdağ	1	Site HSE Manager
Kefgen / Kocaeli	1	Site HSE Manager





# POWERWIND

Your power in wind

## Headquarters

Powerwind Rüzgar Türbinleri Servis San. Tic. Ltd. Şti.

Adalet Mah. Manas Bulvarı No:47/B Folkart Towers D:2601 Bayraklı / İzmir / Türkiye

Tel: +90 232 502 14 14

[www.powerwindservice.com](http://www.powerwindservice.com) / [info@powerwindservice.com](mailto:info@powerwindservice.com)

## Branches

### USA

**POWERWIND ENERGY INC. USA**  
1510 H Street NW, Ste 711,  
Washington,  
District of Columbia 20005

### GERMANY

**POWERWIND ENERGY**  
Butzweilerhofallee 3, 50829  
Cologne Germany

### NETHERLANDS

**POWERWIND ENERGY**  
Avenue Ceramique 221, 6221 KX,  
Maastricht, the Netherlands

### Crane Branch

Panayır, İstanbul Cd 473/1-2, 16250 Osmangazi / Bursa / Türkiye